2	4 HOUR GENERATION CHECKLIST Apple 1	SUFOFRAIS SON WORK?	CHA-RDR69	3000 41R00	16000100 / 4	<u>31 °C</u>	SEC M	" /m	20(g0)
ITEM	TASKS REQUIRED		H-HOUR START	H-HOUR COMP	ACTUAL TIME COMP	TIM	E_COMP SEC	CP CA	LLED
1	MAINTENANCE ALERTED			H-24	1010				
2	DCM MEETING			H-23	0930				
3	MAINT SECURE NITROGEN, OXYGEN			H-23	1110				7. OK
4	PCL SECURE TRUCKS			H⇒23	1110			* F. C.	
5	START MISSICN AIRCRAFT PREFLIGHT		H-22:30	H-00:30	1040		A		17.74.77
6	RECEIVE FUEL LOAD FROM FLIGHT PLANNING			H=22:30					
7	RECEIVED 25X1A			H-22	1210				
8	TEB AND REFUEL	, , , , , , , , , , , , , , , , , , , ,	H=22	H=19	1510	1345	1230	1400	4/40
9	ARC-50 CODES RECEIVED			H=22	1210				1400
10	COMMO AND IFF PREFLIGHT		H=22	H=18	1610	1100	1000		75.7
11	SELECT RECOVERY CREW AND GIVE TO D	OM .	H=20	H=16				$i_{i,j}$	ire en
12	INS PREFLIGHT		H-18	H=16	1810	Maria and the second			4-
13	4	25X1D	H-16	H=13	2110	1710	0900	17/5	1030
14,	PACKAGE DATA RECEIVED	and the state of t	1 11410	H-13:45	A	14113	, 135 0		1400
15	PACKAGE LOADED (CALL SECURITY BEFOR	E MOVING PACKAGE)	H=13	H=08:30	0140	0030		0115	0115
16		25X1D	Hell	0=0830	0140	GAN'S SOLD MALL SERVICE COMMISSION	2300		100
17	POL SEND	25X1A	and the law or an		general de la company de l La company de la company de		STATE OF CHEST STATE		
18	LOX TOP OFF	25/1/4	H=L	H=10:45 H=03:30	0640	2/00	2200		Aug (a)
19	NITHOGEN TOP OFF 25X1D		He/s	H=03:30	0640	TY CHECKSON THE CHEST AND A STATE OF THE CHEST	0650	# T	
20	AIECRAFT STATUS BRIEF: CC, INS,	PKG & DCM C0640	ii-03:30	H=3	0810			191. 5	
21	START INS WARMUP	THE RESIDENCE OF CAMERIES AND ADDRESS OF THE PARTY OF THE	1.1.00,,00	H-03:30	Commencer and Commencer Co	0640	0440	0645	A((1)
22	INSTALL CSC MAGAZINE IN NOSE		H-03:30	-	07/0	07/0	THE RESIDENCE AND ADDRESS OF	7070	2030
23	INS DATA TAPE LOADING				0810		7000		
	PACKAGE I HELIUM PURGE Q-BAY		H-02:30		0940				
	PERSONAL EQUIPMENT LOADED			H=00:30	0810		100		5.00
	MAINT CALL SECURITY TO STERLIZE COCKPIT		H-02:15	H=2 H=01:50	-				
	COCKPIT SET UP PER CODE SHEET		1	H-01:50	0820		S M		
	VIEWFINDER LOADED WITH FILM Approve	CIM BODGO	INDUL SOU		64 5	1 1 1 1 1			
50	ENCINEER CHECK AIRCRAFT	SU FOI REIEASE ZUUZIUDITS:	## -01 130	and the same of the same of the	0910		rijaliy a ya Langu dinte t		
AND MARKET TO	ти также в бил всет на выпушните некомендения вочейникования повет учени прилаг. Симент отказ да о на драгов доба в населе	መ ም ነውም (የሲያናቸውቸውን ተግ ነውን መጀብላው የዚህን "ማሪያውን ነርናርን" አስፕላቶቸውል የብለው አስተልነት የተልነፉ የተልነፉ	and many comments of the	e de la companya de l	2710		FOR THE PARTY OF		AREA PART

4	HOUR GENERATION CHECKLIST (CONTROL OF CHECKLIST CONTROL OF CHECKLIST (CONTROL OF CHECKLI	CIA REPORT	Bookstro	016000700	46-[3]	SEC	w	
			H-HCUR COMP	ACTUAL	TIME COMP		C.P. CALLE	
	TASKS REQUIRED	START	OOM	ELAF.	PRI	SEC	PRI	SEC
	ENGINE START		H-00:30					
l	TAXI		H=00:20	0950				
L	RECOVERY GEAR IN PLACE		H+1	1110				
I				1411				
	POST MISSION LANDING CHECKLIST			1410				
I					10			
I	LAND AWD CCCL AIRCRAFT	I+00:00	L+00:30	1440		÷.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	2	
-	SECURE ACFT AND SERVICE ENG CIL	1400:30	I+01:15	1525				
	25X1D	L+0030	I+01:15	And the last of th				
Treasure.	REMOVE VIEWFINDER FILM STRIP AND MAPS	I#00:30	L+01:15	1525	17. T M	in the		
Acres (Prof. pr	25X1D			1525				
200	MAINTENANCE DEBRIEF							
	25X1D	L+01:00	1+01:15	1525	(interpreted		ap k ikir.	A CONTRACTOR
1	NOVE ARTICLE INTO HANGAR 25X1D			1540			Suite in Product	Greens 198
٠.	(NOTIFY SECURITY TO GLOBE HANGAR DOCKS)	L+01:30	1.+02:30	1640	1445			
1	DCGH FCR 25X1A		1::03:30		327			
Con Michael	CO	F. M. C.		1825	and the	coatae f	M ATEMATIC	010-74
and the same	"TAKE" TO SUPPLY (NOTIFY SECURITY BEFORE MOVING TO SUPPLY	()	I#05:00		1,000			
S americ	PACKAGE SUBMIT 25X1A	THE PARTY OF THE P	L+05:00	1910	1550	A THE RESERVE OF SHAPE AND ADDRESS OF THE PARTY.	4/6	
COMME IN	SECURITY 25X1D	THE PARTY OF A PROPERTY OF THE PARTY OF THE	L+05:00	The property of the same of th		in is i da		
-	RUN TO SECURITY		I.+05:00					
ALC MONE SAL	SECURITY		1+09:00	The state of the s			1.00	
1	ING SUBMIT 25X1A		THE REAL PROPERTY AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS	0010	1630			